

## Leamington Spa, Warwickshire

## Insurance Assessment Project Value | £500



**RMC Water** was instructed to carry out a detailed drainage investigation due to a major basement flooding to a large property in Leamington Spa.

Using CCTV electro location and other survey techniques we were able to isolate the problem area and identify the drainage runs which roots had affected. This has caused the surface water sewers to flood overland and into the basement causing thousands of pounds worth of damage.

Using all the data gathered from the survey, design options were presented to ensure the drainage system was repaired to the most cost effective solution.

**RMC Water** ensured all regulations were met and the new system was installed in a short time frame to ensure the risk of reoccurring flooding to the property was reduced.



**RMC Water** ensured all regulations were met and the new system was installed in a short time frame